
Assembly Instructions INDUSTRIAL SERVICE CART

MODEL

SC-5000 SC-6000 2W423 2W425

PARTS LIST

REFERENCE Letter	QUANTITY AND Description	PART NUMBER 2W423	PART NUMBER 2W425
A	☐ 1 Upper Tray (w/o caster hole)	2W424	2W426
В	☐ 1 Lower Tray (with caster hole)	SC5000LT	SC6000LT
С	☐ 4 Posts	SC5000CP	SC5000CP
D	 2 Caster Mounting Plates 	SC5000CMP	SC6000CMP
E	☐ 2 Swivel Casters	CA5125S	CA5125S
F	☐ 2 Rigid Casters	CA5125R	CA5125R
G	☐ 2 Handle Brackets	SC5000HB	SC5000HB
Н	☐ 1 Tubular Handle	SC5000TB	SC6000TB
	☐ 32 1/4 - 20 x 1/2" Machine Screws	F14205S	F14205S
	☐ 16 1/4 x 20 Grade 5 Hex Bolts	F142058G	F142058G
	☐ 16 1/4" Split Washers	F14SW	F14SW
	☐ 48 1/4 x 20 Hex Nuts	F1420N	F1420N



TOOLS NEEDED FOR ASSEMBLY

1 - 7/16" open end wrench, 1 - blade type screwdriver

HOW TO ASSEMBLE

- Bolt lower tray to 4 posts at matching holes, using (16) 1/4 20 x 1/2" Machine Screws and Hex Nuts.
- Bolt upper tray to posts. Do not insert 2 bolts at position A until ready to attach handle brackets. Use 1/4 - 20 x 1/2" Machine Screws and Hex Nuts.
- Attach casters through holes in lower tray. Place caster mounting plates (D) between caster top plate and lower tray before inserting bolts, using (16) 1/4 x 20 Hex Bolts, (16) Split Washers and (16) Hex Nuts. (See Detail 2).
- Bolt one handle bracket (G) to post at position A, bolting through post, bracket and upper tray. Use 1/4 - 20 x 1/2" Machine Screws and Hex Nuts.
- Insert tubular handle (H) over embossed section of bracket. (See Detail 1).
- Place second handle bracket into tubular handle and bolt to post, using 1/4 - 20 x 1/2" Machine Screws and Hex Nuts.
- Check for squareness and tighten all nuts and bolts.

SAFETY INSTRUCTIONS

Use this product only in accordance with manufacturers intended use. Weight must be evenly distributed and balanced.

